BMW X4 M40d

WBA4M**********

Vehicle specifications

Brand BMW	Model X4 M40d	Body type SUV	Year 2021	Steering Left	Capacity 3.000 cm³
Fuel Diesel	Transmission Automatic	Drive type AWD	Color Silver	Doors 5	Power 340 PS (250 kW)

Generated on 02.11.2026

Mileage — No inconsistencies

We found 36 mileage records.

Damages — Damages found

We found 1 damage record.

Total loss — No total loss

We found no total loss records.

Commercial use — No records

We found no commercial use records.

Historical images — No images

We found no historical images of the car.

Theft registry — No records

We found no theft records.

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.


Mileage check

Track how the mileage evolves over time and any discrepancies between records, when they appear.

No inconsistencies

Note

- The chart shows the available mileage records. The absence of discrepancies does not guarantee the vehicle's actual mileage.



- Last known mileage: 134.482 km
- 36 mileage records found
- Average: about 27.400 km per year

Damage history

See affected parts and estimated cost, based on available data.

Damages found

Note

- Minor damages usually don't affect vehicle safety and don't cause structural problems.



Romania • 07.2025

Recorded damage

Estimated repair cost

562 EUR – 749 EUR

Disclaimer, Damages section

Most damage records come from external sources such as evaluations, inspections, repairs, auctions, claim files, or other events reported by third parties. This information may indicate that the vehicle was inspected, evaluated, repaired, or involved in an event that generated estimated or documented costs.

The displayed values are estimates or figures reported at that moment in time and may vary depending on country, workshop, evaluation method, parts cost, and labor. A reported damage does not automatically mean a major accident, and the absence of reported damages does not guarantee that the vehicle has been free of damage, repairs, or interventions.

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

Service history

A service history shows you how the car has been maintained over time.

Note

- The service history is based on the data available and may contain entry errors, translations, or incomplete descriptions. Verify the information against the car's documents or at an authorized service center.

	Date	Mileage	Country	Description
2026	04/2026	134.470 km	Romania	Service visit
	04/2026	134.470 km	Romania	Brake fluid change, Check hood gas struts
	04/2026	134.482 km		Service check
2025	11/2025	130.048 km	Romania	Air filter replacement, Engine oil change
	09/2025	128.368 km	Romania	Service visit
	06/2025	120.558 km	Romania	Rear brake service
	04/2025	116.388 km	Romania	Engine oil change, Fuel filter replacement, Air filter replacement, Microfilter replacement
2024	09/2024	105.066 km	Romania	Engine oil change, Air filter replacement
	09/2024	104.959 km	Germany	Service visit
	09/2024	104.964 km	Germany	Technical inspection
	05/2024	104.881 km	Germany	Used vehicle inspection, Used vehicle preparation
	05/2024	104.881 km	Germany	Service visit
	03/2024	99.659 km	Germany	Service visit
	03/2024	99.659 km	Germany	Brake fluid change, Check hood gas struts
	03/2024	99.659 km	Germany	Standard service scope, Brake fluid service
	03/2024	99.659 km	Germany	Windshield replacement, KAFAS camera service, Exterior car wash
	03/2024	99.659 km	Germany	Standard service scope, Brake fluid service
	02/2024	95.243 km	Germany	Service visit
	02/2024	95.243 km	Germany	Engine oil change, Microfilter replacement
	02/2024	95.243 km	Germany	Exterior car wash
	02/2024	95.243 km	Germany	Standard service scope, Engine oil service, Microfilter service, Oil service
	02/2024	95.243 km	Germany	Engine oil service, Standard service scope, Microfilter and carbon canister service
	01/2024	92.621 km	Germany	Service visit
2023	11/2023	83.153 km	Germany	Service visit
	11/2023	83.153 km	Germany	Front brake service
	11/2023	83.154 km	Germany	Standard service scope, Front brake service
	11/2023	83.154 km	Germany	Standard service scope, Front brake service
	10/2023	79.982 km	Germany	Service visit

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

	03/2023	–	Germany	Engine oil service, Vehicle check, Standard service scope, Air filter service, Fuel filter service, Rear brake service, Microfilter and carbon canister service
	03/2023	–	Germany	AC refrigerant line service
	03/2023	63.806 km	Germany	Service visit
	03/2023	63.806 km	Germany	Engine oil change, Rear brake service, Fuel filter replacement, Air filter replacement, Vehicle check, Microfilter replacement
	03/2023	63.809 km	Germany	Replace 4 run-flat tires, Install summer wheels
	03/2023	63.809 km	Germany	Install summer wheels, Balance 4 wheels, Store 4 winter wheels
	03/2023	63.806 km	Germany	Standard service scope, Engine oil service, Fuel filter service, Air filter replacement, Microfilter service, Vehicle check, Rear brake service, Service visit
	03/2023	63.809 km	Germany	Install summer wheels, Balance 4 wheels, Store 4 winter wheels
	03/2023	61.535 km		Service visit
	03/2023	60.454 km		Service visit
2022	09/2022	42.620 km	Germany	Service visit
	09/2022	42.624 km	Germany	Install winter wheels, Balance 4 wheels, Store 4 summer wheels, Automatic car wash, Loaner vehicle service
	06/2022	31.293 km	Germany	Service visit
	06/2022	31.293 km	Germany	Engine oil change, Microfilter replacement
	06/2022	31.293 km	Germany	Standard service scope, Engine oil service, Microfilter service, Service visit
	06/2022	31.293 km	Germany	Engine oil service, Standard service scope, Microfilter and carbon canister service
	04/2022	28.174 km	Germany	Service visit
	04/2022	28.174 km	Germany	Windshield replacement, General body work, KAFAS camera service
	04/2022	28.174 km	Germany	Balance 4 wheels, Install summer wheels, Complimentary wheel change check, Winter wheel storage, Automatic car wash
	02/2022	22.335 km	Germany	Rear differential lock servomotor
	02/2022	22.300 km	Germany	Service visit
2021	12/2021	18.684 km	Germany	Vehicle test, Vehicle diagnosis, Battery charging, General electrical system service
	12/2021	18.684 km		Service visit
	12/2021	17.082 km	Germany	Rear differential lock control unit
	12/2021	17.076 km		Service visit
	12/2021	17.076 km		Service visit

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

09/2021	9.480 km	Germany	Service visit
09/2021	6.958 km	Germany	Winter wheel installation, Exterior car wash, Summer wheel storage
09/2021	8.956 km		Service visit
08/2021	–	Germany	Rear right run-flat tire replacement
08/2021	6.965 km		Service visit
08/2021	6.274 km		Service visit
08/2021	6.274 km	Germany	Vehicle test, rear silencer replaced, rear bumper and trim replaced, PDC sensor replaced, rear bumper painted, license plate replaced
07/2021	5.522 km	Germany	Service visit
07/2021	5.522 km	Germany	Paintwork
05/2021	–	Germany	Pre-delivery inspection

Specifications and equipment

Find out how the car left the factory. We check the full equipment list.

Note

- Compare the equipment and specifications in the report against the car's actual configuration. Differences may indicate later modifications or items advertised in a listing but missing from the car.

01AG Larger fuel tank	01CA COP-relevant vehicle selection	01CB CO2 equipment
01CE Brake energy recuperation	0230 EU-specific equipment	0248 Heated steering wheel
0258 Run-flat tires	02NH M Sport brake	02NQ 21" M light-alloy wheels V-spoke 726I
02PA Locking wheel bolts	02T4 M Sport differential	02TB Sport automatic transmission
02VB Tire pressure monitoring	02VF Adaptive M suspension	0302 Alarm system
0320 Model designation deletion	0321 -	0322 Comfort access
03DS BMW Display Key	03DZ Deletion of additional lettering	03KA Acoustic comfort glazing

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

0420	0423	0428
Sun protection glazing	Velour floor mats	Warning triangle and first aid kit
0430	0431	0459
Auto-dimming mirrors	Interior auto-dimming mirror	Electric seat adjustment with memory
0481	0488	048Z
Sports seats	Lumbar support	local description not available
0493	04AW	04HA
Storage compartment package	Sensatec instrument panel	Heated front and rear seats
04K7	04U0	04UR
Aluminium Rhombicle interior trim	Galvanic embellisher for controls	Ambient interior lighting
0534	0536	0548
Automatic air conditioning	Auxiliary heating	Kilometre speedometer
0552	05A1	05AC
Adaptive LED headlights	LED fog lights	High-beam assistant
05AL	05AT	05DA
Active Protection	Driving Assistant Plus	Passenger airbag deactivation
05DN	0610	0654
Parking Assistant Plus	Head-up display	DAB tuner
0688	06AE	06AF
Harman/Kardon surround sound system	Teleservices	Emergency call
06AK	06C4	06NW
ConnectedDrive Services	Digital Professional I	Wireless charging
06U3	06U8	06WD
BMW Live Cockpit Professional	Gesture control	WLAN Hotspot
0710	0715	0760
M leather steering wheel	M Aerodynamics package	High-gloss Shadow Line

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

0775	07M9	07R7
Anthracite headliner	High-gloss Shadow-Line	Innovation package
0801	0851	0879
German version	German language version	German owner's manual
08KA	08R9	08TF
Oil service interval 24 months / 30,000 km	Refrigerant R1234yf	Active pedestrian protection
08TR	0925	09AA
Decoding additional functions	Dummy-SALAPA	Outer skin protection
09D5	09D6	09D7
Entertainment package	Driving experience package	Winter joy package
A090	A83	MANL
-	Glacier Silver metallic paint	Vernasca leather black with blue stitching

Market value

Find out whether the car's price is in the
right range for the current market.

Note

- The displayed value is indicative and does not represent a purchase or sale offer. The actual price may vary depending on the car's condition, equipment, history, and negotiation.

Current market value for BMW X4 M40d

Determined by analyzing the price of a car model from the same year, in the country where the report was generated. We examine data from the last 6 months.



certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

Theft check

Find out whether the vehicle appears as stolen
or recovered in the verified databases.

No records

Note

- The check is based on the sources displayed in this section. The absence of a record indicates that the vehicle does not appear as stolen in the verified databases.

What we checked:

Theft history

- No theft records were found for this vehicle.

The check was performed in the available databases for stolen vehicles from:

Private database · Romania · Slovenia · Italy · Czech Republic · Slovakia · Hungary

Commercial use

See whether the vehicle has been used commercially.

No records

Note

- The check is based on the available commercial-use sources. The absence of a record indicates that the vehicle does not appear in the verified databases as having been used commercially.

Taxi

- No record found

We found no records indicating this vehicle was used as a taxi

Rental

- No record found

We found no records indicating this vehicle was used as a rental

Transport

- No record found

We found no records indicating this vehicle was used as a transport vehicle

Police

- No record found

We found no records indicating this vehicle was used by the police

Demo

- No record found

We found no records indicating this vehicle was used as a demo vehicle

Driving school vehicle

- No record found

We found no records indicating this vehicle was used for driving lessons

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.


Emissions and pollution standard

See the manufacturer-declared CO_2 emissions and the European pollution standard for this model.

Data available

Note

- High CO_2 emissions don't automatically indicate a problem. They can be normal for cars with large engines, heavier weight, all-wheel drive, or sporty performance.



Timeline

An overview of the entire report. All events are listed chronologically for a quick history review.

58 records saved

Note

- Events are displayed chronologically, from the most recent to the oldest. The period covered depends on the data available for this vehicle.

04.2026 Romania

Service visit

The car's data was read from the key during a service visit.

04.2026 Romania

Maintenance carried out

A periodic maintenance operation was recorded.

11.2025 Romania

Maintenance carried out

A periodic maintenance operation was recorded.

09.2025 Romania

Service visit

The car's data was read from the key during a service visit.

07.2025 Romania

Damage recorded

A record linked to a damage event was found in the car's history.

06.2025 Romania

Maintenance carried out

A periodic maintenance operation was recorded.

04.2025 Romania

Maintenance carried out

A periodic maintenance operation was recorded.

09.2024 Romania

Maintenance carried out

A periodic maintenance operation was recorded.

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

09.2024 Germany

Service visit

The car's data was read from the key during a service visit.

09.2024 Germany

Repair carried out

A repair job was recorded.

05.2024 Germany

Repair carried out

A repair job was recorded.

05.2024 Germany

Service visit

The car's data was read from the key during a service visit.

03.2024 Germany

Service visit

The car's data was read from the key during a service visit.

03.2024 Germany

Maintenance carried out

A periodic maintenance operation was recorded.

03.2024 Germany

Repair carried out

A repair job was recorded.

03.2024 Germany

Warranty work

A service operation carried out under warranty was recorded.

02.2024 Germany

Service visit

The car's data was read from the key during a service visit.

02.2024 Germany

Maintenance carried out

A periodic maintenance operation was recorded.

02.2024 Germany

Repair carried out

A repair job was recorded.

02.2024 Germany

Warranty work

A service operation carried out under warranty was recorded.

01.2024 Germany

Service visit

The car's data was read from the key during a service visit.

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

11.2023 Germany

Service visit

The car's data was read from the key during a service visit.

11.2023 Germany

Maintenance carried out

A periodic maintenance operation was recorded.

11.2023 Germany

Repair carried out

A repair job was recorded.

11.2023 Germany

Warranty work

A service operation carried out under warranty was recorded.

10.2023 Germany

Service visit

The car's data was read from the key during a service visit.

03.2023 Germany

Warranty work

A service operation carried out under warranty was recorded.

03.2023 Germany

Service visit

The car's data was read from the key during a service visit.

03.2023 Germany

Maintenance carried out

A periodic maintenance operation was recorded.

03.2023 Germany

Repair carried out

A repair job was recorded.

03.2023

Service visit

The car's data was read from the key during a service visit.

03.2023

Service visit

The car's data was read from the key during a service visit.

09.2022 Germany

Service visit

The car's data was read from the key during a service visit.

09.2022 Germany

Repair carried out

A repair job was recorded.

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

06.2022 Germany

Service visit

The car's data was read from the key during a service visit.

06.2022 Germany

Maintenance carried out

A periodic maintenance operation was recorded.

06.2022 Germany

Repair carried out

A repair job was recorded.

06.2022 Germany

Warranty work

A service operation carried out under warranty was recorded.

04.2022 Germany

Service visit

The car's data was read from the key during a service visit.

04.2022 Germany

Repair carried out

A repair job was recorded.

02.2022 Germany

Warranty work

A service operation carried out under warranty was recorded.

02.2022 Germany

Service visit

The car's data was read from the key during a service visit.

12.2021 Germany

Repair carried out

A repair job was recorded.

12.2021

Service visit

The car's data was read from the key during a service visit.

12.2021 Germany

Warranty work

A service operation carried out under warranty was recorded.

12.2021

Service visit

The car's data was read from the key during a service visit.

12.2021

Service visit

The car's data was read from the key during a service visit.

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.

09.2021 Germany

Service visit

The car's data was read from the key during a service visit.

09.2021 Germany

Repair carried out

A repair job was recorded.

09.2021

Service visit

The car's data was read from the key during a service visit.

08.2021 Germany

Repair carried out

A repair job was recorded.

08.2021

Service visit

The car's data was read from the key during a service visit.

08.2021

Service visit

The car's data was read from the key during a service visit.

08.2021 Germany

Repair carried out

A repair job was recorded.

07.2021 Germany

Service visit

The car's data was read from the key during a service visit.

07.2021 Germany

Repair carried out

A repair job was recorded.

05.2021 Germany

Maintenance carried out

A periodic maintenance operation was recorded.

01.2021 Spartanburg, South Carolina, United States

Was manufactured

Indicates the production center, assembly plant, or the associated manufacturer's headquarters.

certcar

This Certcar PDF report contains the information available at the moment the report was generated. For the most up-to-date data, we recommend consulting the digital report in your Certcar account. The information comes from external sources, partner databases, and/or available official sources, and their availability and accuracy may vary depending on the vehicle, country, and reported history. Certcar cannot guarantee that the report includes all events in the vehicle's history and is not responsible for changes that occur after the report generation date.